

**WALBRIGDE LB 4X 05-103-08736**

Plug and Abandon

MIRU workover rig and aux equipment - ND WH & NU 7 1/16" 5K Class II modified BOPs & Test.

POOH & LD equipment (7" Loc Set Packer & Bare tbg).

PU & RIH w/ BHA & Work String, Cleanout to PBTD at 6413', POOH.

RIH w/ CBL from 6400 - 0, estimated TOC at 1180'

RU PLS & RIH w/ CICR and set 50' above the perms @ 5865'.

RIH w/ WS & Sting into the CICR & Establish injection rate.

- either Pump cement, minimum to plug the Weber: 8 bbls or 37 sxs .

- or Pump cement, maximum to plug to PBTD: 33 bbls or 162 sxs

Pull out of retainer, dump cement on CICR & reverse clean. POOH. 2 bbls or 9 sxs

RIH tag cement, circulate PKR fluid ( 55 gal CRW132/ 100 bbl water) & POOH to 2777'.

Spot minimum 100' Balanced plug across 9-5/8" shoe @ 3026' & reverse clean, POOH. 10 bbls or 48 sxs

RIH Tag cement, circulate PKR fluid & POOH

ND BOPs and NU Tubing top flange. Spot balanced Plug at surface: 10 bbls or 48 sxs

Roustabouts remove cellar, clean up location, flush and remove flowlines and re-seed as needed.

---