

<b>FORM</b> <b>6</b> Rev 12/05	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109		DE ET OE ES
			Date Received:  06/29/2011  Document Number:  2567932

**WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.  
 A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: <u>96340</u>	Contact Name: <u>JACK M FINCHAM</u>
Name of Operator: <u>WIEPKING-FULLERTON ENERGY LLC</u>	Phone: <u>(303) 906-3335</u>
Address: <u>4600 S DOWNING ST</u>	Fax: <u>(303) 761-9067</u>
City: <u>ENGLEWOOD</u> State: <u>CO</u> Zip: <u>80113</u>	Email: <u>FINCHAM4@MSN.COM</u>
<b>For "Intent" 24 hour notice required, COGCC contact:</b>	
Name: <u>QUINT, CRAIG</u>	Tel: <u>(719) 767-8939</u>
Email: <u>craig.quint@state.co.us</u>	

API Number <u>05-017-07648-00</u>	Well Name: <u>SARAH</u>	Well Number: <u>5</u>
Location: QtrQtr: <u>NWNE</u> Section: <u>36</u> Township: <u>14S</u> Range: <u>46W</u> Meridian: <u>6</u>	County: <u>CHEYENNE</u> Federal, Indian or State Lease Number: <u>00/7297</u>	
Field Name: <u>WILDCAT</u>	Field Number: <u>99999</u>	

Notice of Intent to Abandon       Subsequent Report of Abandonment

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 38.794240 Longitude: -102.507050

GPS Data:  
 Date of Measurement: 03/09/2010 PDOP Reading: 2.5 GPS Instrument Operator's Name: KEITH WESTFALL

Reason for Abandonment:     Dry     Production for Sub-economic     Mechanical Problems  
 Other \_\_\_\_\_

Casing to be pulled:     Yes     No    Top of Casing Cement: \_\_\_\_\_

Fish in Hole:     Yes     No    If yes, explain details below

Wellbore has Uncemented Casing leaks:     Yes     No    If yes, explain details below

Details: \_\_\_\_\_

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
MORROW	5380	5388			
Total: 1 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	13+3/8	12+1/4	54.5	414	415	414	0	
1ST	7+7/8	4+1/2	10.5	5,568	200	5,568	4,050	

### Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 5320 with 10 sacks cmt on top. CIPB #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged:   
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged:   
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged:   
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged:   
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged:

Perforate and squeeze at 2500 ft. with 40 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at 2200 ft. with 40 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at 1800 ft. with 40 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 (Cast Iron Cement Retainer Depth)

Set 50 sacks half in. half out surface casing from 464 ft. to 0 ft. Plug Tagged:   
 Set 15 sacks at surface  
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker:  Yes  No  
 Set 5 sacks in rat hole Set 5 sacks in mouse hole

#### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_  
 \*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_  
 Type of Cement and Additives Used: \_\_\_\_\_  
 Flowline/Pipeline has been abandoned per Rule 1103  Yes  No \*ATTACH JOB SUMMARY

Technical Detail/Comments:  
 \_\_\_\_\_

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: JACK M FINCHAM  
 Title: AGENT Date: 6/28/2011 Email: FINCHAM4@MSN.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 6/29/2011

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_ Expiration Date: 12/28/2011

- 1) Provide 24 hour notice of MIRU to Craig Quint at 719-767-8939 or e-mail at craig.quint@state.co.us.
- 2) Plug Verification: 40 sack plug at 2500' – tag or use retainer, 50 sack plug at 464' – tag or use retainer (or cement to surface as proposed increase cement sx as needed), 15 sack plug at surface - Fill casing and annulus from 50' up (if previous plug was not to surface).
- 3) Submit Form 5, 5A and logs with or prior to Form 6 - Subsequent Report of Abandonment.

### **Attachment Check List**

<b>Att Doc Num</b>	<b>Name</b>

Total Attach: 0 Files

### **General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Engineer	Expedited due to operator has rig waiting.	6/29/2011 5:14:50 PM

Total: 1 comment(s)