

- 1 Prepare location for rig to move onto.
- 2 Call Foreman and/or Lead Operator before rig up to isolate any production equipment.
- 3 MIRU WO rig. Kill well, as necessary with 2% KCl water w/ biocide. ND wellhead. NU BOP's. Unseat landing joint and lay down.
- 4 TOO H tubing to set cement plug.
- 5 MIRU wireline. RIH with 5K CIBP and set at 4480' KB. Dump 2 sx of cement on top of CIBP and POOH.
- 6 ND BOP's and tubing head. Unland casing from slips and work casing. TIH w/ free point tool to find free casing and POOH. TIH with chemical cutter to cut csg 50' above free point. Estimated TOC 4120' KB.
- 7 RDMO wireline.
- 8 TOO H and LD 2-7/8" casing.
- 9 TIH with 2 3/8" working string to casing stub. MIRU cementing services. Set 100 ft balanced plug across cement stub.
- 10 PUH with 2 3/8" working string to ~ 735'. Set cement plug 50 ft below surface shoe to surface.
- 11 Cut surface casing 5 ft below ground level and weld on cap.
- 12 RDMO WO rig.
- 13 Submit Form 6 to COGCC.