

JEPSEN 32-2

05-123-33803

SESW SEC 2 3N 65W

NOTICE OF INTENT TO ABANDON PROCEDURES

- 1 Obtain surface land clearance, including notifying surface owner of our intentions
- 2 Prepare location for WO rig move and rig up. Spot 16 jnts of 2-3/8" 4.7# J-55 8RD EUE to tag cement top and for pumping cement plug.
- 3 Communicate with Foreman and or Field Coordinator before rig up to isolate any production equipment.
- 4 MIRU WO rig. ND wellhead. NU BOPs.
- 5 PU 2-3/8" tubing and TIH to tag cement top (Estimated top is 450' KB). Please contact engineering if cement top is below 475' KB.
- 6 TOOH one joint and prepare for cementing job.
- 7 MIRU cementing services.
- 8 Pump cement as follows (based on end of tubing @ 420'): Use class G 15.8# cement with 2% CaCl (Calcium Chloride) in the cement. After establishing circulation with fresh water, pump 150 sks cement (130 sks + excess). Place cement to surface.
- 9 TOOH with 2-3/8" tubing and LD.
- 10 Top off cement to surface in 8-5/8" surface csg (approx. 4 sks).
- 11 RDMO cementing services. Let cement set minimum 24 hrs.
- 12 Ensure there is no pressure at surface. ND BOP. RDMO WO rig.
- 13 Cut surface casing 5 ft below ground level and weld on cap. Properly abandon all flow lines and surface equipment.
- 14 Submit Form 6 with COGCC.