

## WORKOVER PROCEDURE

**WELL NAME:** LEHFELDT C27-11 **DATE:** 7/17/2012  
**LOCATION:**  
Qtr/Qtr: NESW Section: 27 Township: 4N Range: 64W  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-15430

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:**

Surface Csg:	<u>8 5/8" 24# @ 314'</u>	KB Elevation:	<u>4692</u>
Surface Cmt:	<u>100 sx cement to surface</u>	GL Elevation:	<u>4682</u>
Long St Csg:	<u>2 7/8" 8.70# @ 7044'</u>	TD:	<u>7044</u>
Long St Cmt:	<u>290 sx TOC 5910'</u>	PBTD:	<u>6995</u>
Long St Date:	<u>2/19/1992</u>		

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): CODELL PERFS 6843' - 6856'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1 1/4" 2.33# 207 JTS @ 6813' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/1 1/4" tubing. And lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6743', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5800'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to 5800' Pump 100 sx stub plug. Wait 4 hrs, tag plug.
- 6) Pump 50 sx courtesy plug @2500'. POOH w/workstring to 420'. Pump approx 260 sx shoe plug, cement to surface. POC
- 6) Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.