

WORKOVER PROCEDURE

WELL NAME: STATE A 36-99HZ DATE: 10/23/2012
LOCATION: Qtr/Qtr: NWNW Section: 36 Township: 6N Range: 64W
COUNTY: WELD STATE: CO API #: 05-123-32261

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 9 5/8" 36# @668.3' KB Elevation: 4653
Surface Cmt: 292 sx GL Elevation: 4629
Intermediate Csg: 7" 26# @7165.1' TD: 12140
Intermediate Cmt: 600 sx PBTD: _____
Production Csg: 4 1/2" 11.6# 6028.9' - 12140'
Production Cmt: _____
Production csg Date: 11/14/2010

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Interval 7513' - 11928'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70# J-55 tbg @ 5979' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tubing. And lay down.
- 3) Set CIBP @ 7200' by pumping down or set w/ tubing
- 4) RIH w/ workstring, pump 25 sx balance plug above CIBP
- 5) POOH w/ workstring, set balanced plug from 5928' - 6128' (approx 50 sx)
- 6) POOH w/ workstring to 2500', pump 40 sx plug
- 7) POOH w/ workstring.
- 8) Unland casing. Cut casing off +/- 1000'. POOH with casing laying down on trailer.
- 9) RIH w/ workstring to pump 100 sx stub plug from 900' - 1100'. If maintain circulation, do not need to tag plug.
- 10) POOH w/ workstring to 770'. Pump approx 350 sx shoe plug. Cement to surface.
- 11) RIH. Tag plug. Add cement if needed.
- 12) Cut surface casing off 6'-8' below ground.
- 13) Clean up location. Reclaim location. RDMO.