

WORKOVER PROCEDURE

WELL NAME: SWANSON FARMS 4-28 EG DATE: 10/11/2012

LOCATION: _____

Qtr/Qtr: NENE Section: 28 Township: 6N Range: 65W

COUNTY: WELD STATE: CO API #: 05-123-14925

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____

(Please notify Engineer of any major Do not start operations until: _____

changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 363' KB Elevation: 4710

Surface Cmt: 215 sx GL Elevation: 4699

Long St Csg: 4 1/2" 10.5# @ 3767' TD: 3772

Long St Cmt: 150 sx PBTD: 3642

Long St Date: 3/4/1991

Plug Back (Sand or CIBP): _____

Perforation Interval (1): PARKMAN PERFS 3621' - 3626'

Perforation Interval (2): _____

Perforation Interval (3): _____

Tubing: 2 3/8" 4.7# J-55 @ 3612' Rods: 7/8", 3/4" Rods @ 3592'

Pump: 2" Pump

Misc.: Tubing Anchor @ 3496'

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ Rods. And lay down.
- 3) Release tubing anchor. POOH w/ 2 3/8" tbg and lay down.
- 4) RU WL. RIH w/CIBP. Set CIBP @ 3396', dump bail 2 sx of cement on top.
- 5) Unland casing. Cut casing off +/- 3000'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to 3000' Pump (100) sx stub plug. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 463'. Pump approx 200 sx shoe plug. Cement to surface.
- 8) RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.