

WORKOVER PROCEDURE

WELL NAME: THORNTON FARMS 01-05 **DATE:** 10/30/2012

LOCATION:

Qtr/Qtr: SWNE Section: 5 Township: 5N Range: 67W
COUNTY: WELD **STATE:** CO **API #:** 05-123-10778

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA:	Surface Csg: 8 5/8" 24# @ 338'	KB Elevation: 4887
	Surface Cmt: 300 sx	GL Elevation: 4877
	Long St Csg: 4 1/2" 11.6# @ 7575'	TD: 7767
	Long St Cmt: 200 sx	PBTD: 7543
	Long St Date: 8/19/1982	

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perfs 7210' - 7220'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 @ 7201' Rods: _____
Pump: _____
Misc.: **Cement Squeeze 4348' - 4780'. Casing patch @ 4050'.**

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tubing. And lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7110', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 4000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to 4000' Pump (100) sx stub plug. If maintain circulation, do not need to tag plug.
- 6) Pump (50) sx plug @2500'. POOH w/workstring to 438'. Pump approx 200 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.