

WORKOVER PROCEDURE

WELL NAME: SHIVERS 04 **DATE:** 11/8/2012

LOCATION: _____

Qtr/Qtr: SWNE Section: 29 Township: 2N Range: 66W

COUNTY: WELD **STATE:** CO **API #:** 05-123-08775

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____

(Please notify Engineer of any major Do not start operations until: _____

changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 697' KB Elevation: 4908

Surface Cmt: 500 sx GL Elevation: 4895

Long St Csg: 4 1/2" 10.5# @ 4749' TD: 4750

Long St Cmt: 350 sx PBSD: 4698

Long St Date: 10/12/1976

Plug Back (Sand or CIBP): _____

Perforation Interval (1): SUSSEX PERFS 4604' - 4644'

Perforation Interval (2): _____

Perforation Interval (3): _____

Tubing: 2 3/8" 4.70# @ 4618' Rods: _____

Pump: _____

Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tubing. And lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 4504', dump bail 2 sx of cement on top.
- 4) Run CBL to confirm cement coverage to surface.
- 5) RIH w/ workstring to 2500' Pump (40) sx stub plug. If maintain circulation, do not need to tag plug.
- 6) POOH w/workstring to 800'. Pump approx 100 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.