

## WORKOVER PROCEDURE

**WELL NAME:** CLEMONS 13-15 **DATE:** 11/19/2012

**LOCATION:**

Qtr/Qtr: NWSW Section: 15 Township: 4N Range: 64W  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-11032

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

<b>WELL DATA:</b>	Surface Csg: 9 5/8" 36# @ 208'	KB Elevation: 4674
	Surface Cmt: 150 sx	GL Elevation: 4666
	Long St Csg: 4 1/2" 11.6# @ 6903'	TD: 6920
	Long St Cmt: 110 sx	PBTD: 6888
	Long St Date: 3/8/1983	

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 6552' - 6710'  
Perforation Interval (2): Codell Perforations 6818' - 6828  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.7# J-55 @ 6808' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tubing. And lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6452', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to 5500' Pump (100) sx stub plug. If maintain circulation, do not need to tag plug.
- 6) Pump (50) sx plug @2500'. POOH w/workstring to 350'. Pump approx 200 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.