

WORKOVER PROCEDURE

WELL NAME: ADLER 44-10 DATE: 1/8/2013

LOCATION: _____

Qtr/Qtr: SESE Section: 10 Township: 4N Range: 64W

COUNTY: WELD STATE: CO API #: 05-123-10985

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____

(Please notify Engineer of any major Do not start operations until: _____

changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 9 5/8" 36# @ 221' KB Elevation: 4641

Surface Cmt: 185 sx GL Elevation: 4630

Long St Csg: 4 1/2" 11.6# @ 7330' TD: 7342

Long St Cmt: 220 sx PBTD: 7019

Long St Date: 1/22/1983

Plug Back (Sand or CIBP): _____

Perforation Interval (1): Codell Perforations 6765' - 6778'

Perforation Interval (2): _____

Perforation Interval (3): _____

Tubing: 2 3/8" 4.7# J-55 @ 6743' Rods: _____

Pump: _____

Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RU WL. RIH w/CIBP. Set CIBP @ 6665", dump bail 2 sx of cement on top.
- 3) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 4) RIH w/ workstring to pump (100) sx stub plug where casing was pulled. If maintain circulation, do not need to tag plug.
- 5) Pump (50) sx plug @2500'. POOH w/workstring to 350'. Pump approx 200 sx shoe plug. Cement to surface.
- 6) RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.