

WORKOVER PROCEDURE

WELL NAME: FEIT E23-05 **DATE:** 1/29/2013

LOCATION: _____

Qtr/Qtr: SWNW Section: 23 Township: 6N Range: 65W

COUNTY: WELD **STATE:** CO **API #:** 05-123-17728

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 339' KB Elevation: 4738
Surface Cmt: 230 sx GL Elevation: 4728
Long St Csg: 2 7/8" 6.5# @ 7308' TD: 7316
Long St Cmt: 580 sx PBDT: 7270
Long St Date: 2/12/1994

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7018' - 7032'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 1/4" J-55 2.3# @ 6999' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/4" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6918', dump bail 2 sx of cement on top.
- 4) Pump (10) sx plug @2500'. POOH w/workstring to 500'. Pump approx 25 sx shoe plug. Cement to surface.
- 5) RIH. Tag shoe plug. Add cement if needed.
- 6) Cut surface casing off 6'-8' below ground.
- 7) Clean up location. Reclaim location. RDMO.