

**WORKOVER PROCEDURE**

**WELL NAME:** SITZMAN E23-12 **DATE:** 1/30/2013

**LOCATION:** \_\_\_\_\_

Qtr/Qtr: NWSW Section: 23 Township: 6N Range: 65W

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-17854

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_

(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_

changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 339' KB Elevation: 4726

Surface Cmt: 245 sx GL Elevation: 4716

Long St Csg: 2 7/8" 6.5# @ 7164' TD: 7185

Long St Cmt: 775sx/215sx PBSD: 7161

Long St Date: 2/18/1994

Plug Back (Sand or CIBP): \_\_\_\_\_

Perforation Interval (1): Codell Perforations 7014' - 7030'

Perforation Interval (2): \_\_\_\_\_

Perforation Interval (3): \_\_\_\_\_

Tubing: 1 1/2" 2.4# J-55 @ 6995' Rods: \_\_\_\_\_

Pump: \_\_\_\_\_

Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_

**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/2" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6914', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) POOH w/workstring to 440'. Pump approx 200 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.