

WORKOVER PROCEDURE

WELL NAME: BELL L12-24 DATE: 2/5/2013

LOCATION: Qtr/Qtr: C S/2 Section: 12 Township: 3N Range: 66W

COUNTY: STATE: CO API #: 05-123-15853

ENGINEER: LEAH PERKINS 7 Day Notice Sent: Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 559' Surface Cmt: 300 sx Long St Csg: 2 7/8" 6.5# @ 7567' Long St Cmt: 280 sx Long St Date: 7/9/1992 KB Elevation: 7594 GL Elevation: 7538 TD: 7594 PBTD: 7538

Plug Back (Sand or CIBP): Perforation Interval (1): Codell Perforations 7415' - 7442' Perforation Interval (2): Perforation Interval (3): Tubing: Rods: Pump: Misc.: Fish @ 7241' (5.5 jts of 1.25" tbg). 2 Chemical guns on top of fish. Tight Spot in csg @2971'

PRODUCTION STATUS: COMMENTS:

- PROCEDURE: 1) MIRU Workover rig, pump & tank. 2) Attempt to set CIBP @ 7200'. (Prior attempts were not successful). Dump bail 2 sx of cement on top. 3) If CIBP can not be set, set 150' balanced plug above perforations (5-10 sx). (7215' - 7365'). Wait 4 hours, tag plug. 4) Unland casing. Cut casing off +/- 1800'. POOH with casing laying down on trailer. 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug. 6) POOH w/workstring to 660'. Pump approx 300 sx shoe plug. Cement to surface. 7) RIH. Tag shoe plug. Add cement if needed. 8) Cut surface casing off 6'-8' below ground. 9) Clean up location. Reclaim location. RDMO.