

**WORKOVER PROCEDURE**

**WELL NAME:** PETRIKIN A34-16 **DATE:** 2/12/2013

**LOCATION:** \_\_\_\_\_

Qtr/Qtr: SESE Section: 34 Township: 6N Range: 64W

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-13478

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_

(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_

changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 312' KB Elevation: 4670

Surface Cmt: 220 sx GL Elevation: 4659

Long St Csg: 4 1/2" 15.1# @ 6980' TD: 6985

Long St Cmt: 220 sx PBTD: 6839

Long St Date: 6/17/1987

Plug Back (Sand or CIBP): \_\_\_\_\_

Perforation Interval (1): Niobrara Perforations 6551' - 6736'

Perforation Interval (2): Codell Perforations 6826' - 6836'

Perforation Interval (3): \_\_\_\_\_

Tubing: 2 3/8" 4.7# @ 6824' Rods: \_\_\_\_\_

Pump: \_\_\_\_\_

Misc.: **No CBL in well file, on COGCC Website. TOC @ 5981'**

**PRODUCTION STATUS:** \_\_\_\_\_

**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6451', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 440'. Pump approx 200 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.