

WORKOVER PROCEDURE

WELL NAME: WELLS 43-3 DATE: 1/8/2013
LOCATION:
Qtr/Qtr: NESE Section: 3 Township: 5N Range: 63W
COUNTY: WELD STATE: CO API #: 05-123-21157

ENGINEER: LEAH PERKINS 7 Day Notice Sent:
(Please notify Engineer of any major Do not start operations until:
changes prior to work) Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 416' KB Elevation: 4712
Surface Cmt: 295 sx GL Elevation: 4700
Long St Csg: 4 1/2" 11.6# @ 7313' TD: 7483
Long St Cmt: 333 sx PBSD: 6368
Long St Date: 12/23/2002

Plug Back (Sand or CIBP): CIBP @ 6368', 7014', 7050'
Perforation Interval (1): Niobrara Perforations 6468' - 6570'
Perforation Interval (2): Codell Perforations 6650' - 6659'
Perforation Interval (3): J Sand Perforations 7098' - 7108'
Tubing: Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) Circulate sand off of Bridge Plug @6368'. Dump bail 2 sx or pump 10 sx cement plug on top of bridge plug (~100' plug)
3) Unland casing. Cut casing off +/- 3500'. POOH with casing laying down on trailer.
4) RIH w/ workstring to pump (100) sx stub plug where casing was pulled. If maintain circulation, do not need to tag plug.
5) POOH w/workstring to 550'. Pump approx 250 sx shoe plug. Cement to surface.
6) RIH. Tag shoe plug. Add cement if needed.
7) Cut surface casing off 6'-8' below ground.
8) Clean up location. Reclaim location. RDMO.