

WORKOVER PROCEDURE

WELL NAME: LEMONS X6-06 **DATE:** 3/13/2013

LOCATION:

Qtr/Qtr: SENW Section: 6 Township: 2N Range: 65W
COUNTY: WELD **STATE:** CO **API #:** 05-123-15583

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

| | | |
|-------------------|----------------------------------|--------------------|
| WELL DATA: | Surface Csg: 8 5/8" 24# @ 766' | KB Elevation: 4997 |
| | Surface Cmt: 535 sx | GL Elevation: 4987 |
| | Long St Csg: 3 1/2" 7.7# @ 7535' | TD: 7535 |
| | Long St Cmt: 230 sx | PBTD: 7421 |
| | Long St Date: 6/4/1992 | |

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7363' - 7377'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 1/4" 2.33# J-55 @ 7343' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/4" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7263', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 866'. Pump approx 325 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.