

WORKOVER PROCEDURE

WELL NAME: BOLET RED X15-10JI **DATE:** 1/17/2013

LOCATION: _____

Qtr/Qtr: NWSE Section: 15 Township: 2N Range: 65W

COUNTY: WELD **STATE:** CO **API #:** 05-123-20141

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____

(Please notify Engineer of any major Do not start operations until: _____

changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 807' KB Elevation: 4891

Surface Cmt: 565 sx GL Elevation: 4880

Long St Csg: 4 1/2" 11.6# @ 7743' TD: 7751

Long St Cmt: 150 sx PBSD: 7721

Long St Date: 1/22/2001

Plug Back (Sand or CIBP): _____

Perforation Interval (1): J Sand Perforations 7624' - 7672'

Perforation Interval (2): _____

Perforation Interval (3): _____

Tubing: 2 3/8" 4.7# J-55 @ 7587' Rods: _____

Pump: _____

Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7524', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to 5000' Pump (100) sx stub plug. If maintain circulation, do not need to tag plug.
- 6) Pump (50) sx plug @2500'. POOH w/workstring to 907'. Pump approx 400 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.