

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.
 A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

Document Number:
400403948

Date Received:
04/15/2013

OGCC Operator Number: 69175 Contact Name: Jenifer Hakkarinen
 Name of Operator: PDC ENERGY INC Phone: (303) 8605800
 Address: 1775 SHERMAN STREET - STE 3000 Fax: (303) 8605838
 City: DENVER State: CO Zip: 80203 Email: Jenifer.Hakkarinen@pdce.com

For "Intent" 24 hour notice required, Name: PRECUP, JIM Tel: (303) 726-3822
COGCC contact: Email: james.precup@state.co.us

API Number 05-123-16318-00 Well Number: 3
 Well Name: BLACKGOLD
 Location: QtrQtr: SESW Section: 10 Township: 6N Range: 66W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: 55877
 Field Name: EATON Field Number: 19350

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.497222 Longitude: -104.766667
 GPS Data:
 Date of Measurement: 01/18/2010 PDOP Reading: 1.8 GPS Instrument Operator's Name: Brandon Lucason
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: 6380
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|-----------|-----------|-----------|----------------|---------------------|------------|
| CODELL | 7288 | 7298 | | | |

Total: 1 zone(s)

Casing History

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| SURF | 12+1/4 | 8+5/8 | 26 | 403 | 280 | 403 | 0 | CALC |
| 1ST | 7+7/8 | 4+1/2 | 11.6 | 7,429 | 170 | 7,429 | 6,480 | CBL |

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7230 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 50 sks cmt from 6380 ft. to 6390 ft. Plug Type: STUB PLUG Plug Tagged:
Set 200 sks cmt from 3500 ft. to 4200 ft. Plug Type: OPEN HOLE Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set 250 sacks half in. half out surface casing from 760 ft. to 0 ft. Plug Tagged:

Set 10 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Plugging Procedure
Codell
Existing Perforations:
Codell: 7288'-7298'
PBSD: 7411"
8 5/8" 24# Casing set @ 403' cemented w/ 280 sx
4 1/2" 11.6# Casing set @ 7429' cemented w/ 170 sx
Procedure:
1)MIRU wireline
2)RIH w/CIBP set @ 7230'
3)RIH w/dump bailer and dump 2 sx cement on top of CIBP
4)RIH w/casing cutter, cut & pull casing @ ~6380'
5)TIH set 50 sack plug @ casing stub (6380')
6)TIH to tag stub plug
7)TOH to set 200 sack plug @ Parkman/Sussex (~3500'--4200')
8)TOH and set 250 sack cement plug 500' to surface
9)Set 10 sx @ top of surface
10)Cut casing and weld on cap

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Jenifer Hakkarinen

Title: Regulatory Tech Date: 4/15/2013 Email: Jenifer.Hakkarinen@pdce.com

Based on the information provided in the Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:

Date: 4/17/2013

CONDITIONS OF APPROVAL, IF ANY:

Expiration Date: 10/16/2013

- 1) Provide 24-hour notice of MIRU to Jim Precup at (303) 726-3822.
- 2) Provide an "As Plugged" wellbore diagram identifying the specific plugging completed.
- 3) Based on offset water wells, the surface plug shall be provided from 760' to at least 50' within the surface casing shoe. If not brought to surface, this plug shall be tagged and must be 353' or shallower.
- 4) If unable to pull casing, contact COGCC for plugging modifications.
- 5) Properly abandon flowlines as per Rule 1103.
- 6) See plugging changes above.

Attachment Check List

| Att Doc Num | Name |
|-------------|-------------------------|
| 400403948 | FORM 6 INTENT SUBMITTED |
| 400403954 | WELLBORE DIAGRAM |
| 400403956 | WELLBORE DIAGRAM |

Total Attach: 3 Files

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|----------------|---------------------|
| | | |

Total: 0 comment(s)