

WORKOVER PROCEDURE

WELL NAME: DILLARD 04-44 **DATE:** 4/10/2013

LOCATION: _____

Qtr/Qtr: SESE Section: 4 Township: 7N Range: 64W

COUNTY: WELD **STATE:** CO **API #:** 05-123-26342

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____

(Please notify Engineer of any major Do not start operations until: _____

changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 677' KB Elevation: 4878

Surface Cmt: 360 sx GL Elevation: 4866

Long St Csg: 4 1/2" 11.60# @ 7170' TD: 7200

Long St Cmt: 625 sx PBTD: 7153

Long St Date: 10/9/2007

Plug Back (Sand or CIBP): _____

Perforation Interval (1): Niobrara Perforations 6947' - 6966'

Perforation Interval (2): Codell Perforations 7052' - 7064'

Perforation Interval (3): _____

Tubing: 2 3/8" 4.7# J-55 @ 7095 Rods: 76 String (281 Rods) @ 7073'

Pump: _____

Misc.: Tubing Anchor @ 6806'

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ rods and lay down.
- 3) Release tubing anchor. POOH w/ 2 3/8" tbg and lay down.
- 4) RU WL. RIH w/CIBP. Set CIBP @ 6847', dump bail 2 sx of cement on top.
- 5) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 777'. Pump approx 300 sx shoe plug. Cement to surface.
- 8) RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.