

WORKOVER PROCEDURE

WELL NAME: CON GQ07-01 **DATE:** 3/12/2013

LOCATION: Qtr/Qtr: NENE Section: 7 Township: 10N Range: 61W

COUNTY: WELD **STATE:** CO **API #:** 05-123-35654

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 9 5/8" 36# @ 1104' KB Elevation: 5091
Surface Cmt: 514 sx GL Elevation: 5078
Long St Csg: 7" 26# @ 9000' TD: 10372
Long St Cmt: 405 sx PBTD: 7830
Long St Date: _____

Plug Back (Sand or CIBP): **CIBP @ 7830'**
Perforation Interval (1): _____
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: _____ Rods: _____
Pump: _____
Misc.: **Drilled and abandoned - dry hole**

PRODUCTION STATUS: _____
COMMENTS: Existing Cement Plugs: 9611' - 10372' and 8783' - 9589'

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) Run CBL to determine TOC.
- 3) Perforate ~5000' and set CICR (Depth may need adjusted after CBL). Pump 100 sx through CICR. Unsting, pump 25 sx on top of CICR.
- 4) Perforate @ 2500' and set CICR. Pump 100 sx through CICR. Unsting, pump 25 sx on top of CICR.
- 5) Pump approx 500 sx shoe plug from 1200' to surface. Cement to Surface.
(Either perforate @ 1200' and set CICR and circulate to surface. Or pump 1200' plug in 7" and in Annulus with work string.)
- 6) RIH. Tag plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.