

REENTRY PROCEDURE

WELL NAME: WELD COUNTY FA 43-10-7-64 DATE: 4/9/2013

LOCATION: Qtr/Qtr: NESE Section: 10 Township: 7N Range: 64W
COUNTY: WELD STATE: CO API #: 05-123-12478

ENGINEER: Amanda Beck 7 Day Notice Sent: _____
(Please notify Engineer of any major changes prior to work) Do not start operations until: _____
Notice Expires: _____

OBJECTIVE: Reenter and re-plug

WELL DATA: Surface Csg: 8 5/8" 24# 486' KB Elevation: _____
Surface Cmt: 290 SX GL Elevation: 4824'
Long St Csg: 7 7/8" open hole to 5100'; 4 1/2" 11.6# csg 7640' TD: 7650'
Long St Cmt: 375 SX PBTD: 0
Long St Date: 6/21/1985

Plug Info (1) CIBP at 6700' in 4 1/2" casing; 15 sx on top
Plug Info (2) 40 sx in open hole 1300'-1400'
Plug Info (3) 15 sx at surface
Plug Info (4) _____

Tubing: _____ Rods: _____
Pump: _____

Misc.: Base Fox Hills 645'; do not drill out second cement plug, tag TOC@1300' and bring cement to surface

WELL STATUS: Well Abandoned 5/22/90

COMMENTS: Plugging report states: Cut 4' below ground level, Welded plate on top of surface

PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake
- 2) Excavate to expose top of surface casing
- 3) Weld 2" collar to top of 8 5/8" surface casing cap. Make up to collar, pneumatic drill with non-sparking bit. Drill out cap venting possible trapped gas.
- 4) Once verified that no gas exists beneath top of surface casing plate, cut off surface casing below plate with torch, dress up smooth.
- 5) Butt weld 8 5/8" casing to dressed cut, bringing threaded end of casing to ground level.
- 6) Make up to 8 5/8" casing, one 8 5/8" collar and 8 5/8" starter well head
- 7) NU flange adaptor and 5k BOP, test BOP.
- 8) NU and RIH with 6 7/8" cone bit, PU 2 7/8" drill collar, 2 7/8" 8.7# tubing, and TIW valve
- 9) Drill out first cement plug inside surface casing, roll hole clean.
- 10) set RBP inside surface casing
- 11) Once isolation of surface casing is established, with setting of RBP, pressure test surface casing to 200psi
- 12) After pressure test of surface casing, retrieve RBP
- 13) Continue RIH, cleaning out with drilling mud or water and tag top of cement plug @ 1300'
- 14) TOO H with cone bit, drill collars, and 2 7/8" tubing.
- 15) PU and RIH with mule shoe and 2 7/8" tubing to 1300'.
- 16) RU cement crew and pump 490 sxs of 15.8ppg Class G "neat" cement bring cement to surface
- 17) POOH with 2 7/8" tubing. Wait 4 hrs, and tag TOC. If cement has fallen, top off back to surface
- 18) Let cement set over night, verify cement has not settled and is still at surface. RDMO
- 19) Excavate around wellhead to 8' below grade, cut off 8 5/8" casing, weld on cap
- 20) Backfill hole and reclaim surface to original conditions