

WORKOVER PROCEDURE

WELL NAME: GEOFFROY 11-1418 **DATE:** 6/17/2013

LOCATION: _____

Qtr/Qtr: SESW Section: 11 Township: 4N Range: 68W
COUNTY: WELD **STATE:** CO **API #:** 05-123-17880

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 509' KB Elevation: 4978
Surface Cmt: 335 sx GL Elevation: 4967
Long St Csg: 3 1/2" 7.70# @ 7642' TD: 7648
Long St Cmt: 295 sx PBTD: 7635
Long St Date: 12/13/1994

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perfs 7039' - 7054'
Perforation Interval (2): J Sand Perfs 7474' - 7520'
Perforation Interval (3): _____
Tubing: 2 1/16" 3.25# J-55 @ 7463' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7374', dump bail 2 sx of cement on top.
- 4) RIH w/ second CIBP. Set CIBP @ 6939', dump bail 2 sx of cement on top.
- 5) Unland casing. Cut casing off +/- 1500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 609'. Pump approx 225 sx shoe plug. Cement to surface.
- 8) RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.