

WORKOVER PROCEDURE

WELL NAME: CAMENISCH P04-06 **DATE:** 6/17/2013
LOCATION:
Qtr/Qtr: SENW Section: 4 Township: 3N Range: 67W
COUNTY: WELD **STATE:** CO **API #:** 05-123-15630

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA:

Surface Csg:	8 5/8" 24# @ 517'	KB Elevation:	4862
Surface Cmt:	360 sx	GL Elevation:	4852
Long St Csg:	2 7/8" 6.5# @ 7327'	TD:	7344
Long St Cmt:	250 sx	PBTD:	7283
Long St Date:	1/16/1994		

Plug Back (Sand or CIBP): _____
Perforation Interval (1): _____ Codell Perforations 7175' - 7194'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 1/4" 2.33# J-55 @ 7165' Rods: _____
Pump: _____
Misc.: *Packer Type Csg Patch @ 5228'*

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/4" tbg and lay down.
- 3) RIH w/ workstring and pump balanced plug from 7250' - 7050' (~10sx). Wait 4 hours, tag plug.
(Option to set CIBP @ 7075' and dump bail 2 sx of cement)
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 617'. Pump approx 250 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.