

## WORKOVER PROCEDURE

**WELL NAME:** TOLLGATE FARMS 29-12G6 **DATE:** 6/13/2013

**LOCATION:** Qtr/Qtr: NWSW Section: 29 Township: 6N Range: 66W

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-18601

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 7" 17/20# @351' KB Elevation: 4741  
Surface Cmt: 100 sx GL Elevation: 4727  
Long St Csg: 2 7/8" 6.40# @ 7217' TD: 7243  
Long St Cmt: 288 sx PBTD: 7183  
Long St Date: 12/1/1994

Plug Back (Sand or CIBP): CIBP @ 6686' AND RBP @ 6786'  
Perforation Interval (1): Codell Perforations 7096' - 7114'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: \_\_\_\_\_ Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) Unland casing. Cut casing off +/- 3500'. POOH with casing laying down on trailer.
- 3) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 4) POOH w/workstring to 450'. Pump approx 125 sx shoe plug. Cement to surface.
- 5) RIH. Tag shoe plug. Add cement if needed.
- 6) Cut surface casing off 6'-8' below ground.
- 7) Clean up location. Reclaim location. RDMO.