

WORKOVER PROCEDURE

WELL NAME: LILLI UNIT 06-08A **DATE:** 5/31/2013
LOCATION:
Qtr/Qtr: SENW Section: 8 Township: 8N Range: 58W
COUNTY: WELD **STATE:** CO **API #:** 05-123-13875

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 182' KB Elevation: 4787
Surface Cmt: 100 sx GL Elevation: 4778
Long St Csg: 4 1/2" 10.5# @ 6590' TD: 6590
Long St Cmt: 190 sx PBTD: 6570
Long St Date: 3/18/1988

Plug Back (Sand or CIBP): _____
Perforation Interval (1): D Sand Perforations 6420' - 6424'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 6489' Rods: 3/4" Rods (248 rods)
Pump: 1 1/4" BHD Pump
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
 - 2) POOH w/ rods and lay down.
 - 3) Release tubing anchor. POOH w/ 2 3/8" tbg and lay down.
 - 4) RU WL. RIH w/CIBP. Set CIBP @ 6320', dump bail 2 sx of cement on top.
 - 5) Perforate @ 2500' and set CICR. Pump 90 sx through CICR and 10 sx above CICR.
 - 6) Unland casing. Cut casing off +/- 1000'. POOH with casing laying down on trailer.
 - 7) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
 - 8) POOH w/workstring to 300'. Pump approx 125 sx shoe plug. Cement to surface.
 - 9) RIH. Tag shoe plug. Add cement if needed.
- Cut surface casing off 6'-8' below ground.
- Clean up location. Reclaim location. RDMO.