

WORKOVER PROCEDURE

WELL NAME: KARCH BLUE D24-12 **DATE:** 6/27/2013

LOCATION: _____

Qtr/Qtr: NWSW Section: 24 Township: 3N Range: 64W

COUNTY: WELD STATE: CO API #: 05-123-16170

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____

(Please notify Engineer of any major _____ Do not start operations until: _____

changes prior to work) Notice Expires: _____

OBJECTIVE: _____ P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 584' KB Elevation: 4779

Surface Cmt: 150 sx GL Elevation: 4769

Long St Csg: 2 7/8" 6.5# @ 6998' TD: 7023

Long St Cmt: 250 sx PBTD: 6746

Long St Date: 10/31/1992

Plug Back (Sand or CIBP):

Perforation Interval (1):	Codell Perforations 6859' - 6869'
---------------------------	-----------------------------------

Perforation Interval (2):

Perforation Interval (3):

Tubing: 1 1/4" tbg @ 6853' Rods:

Pump: _____

Misc.: _____

PRODUCTION STATUS:

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/4" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6759', dump bail 2 sx of cement on top.
(If can not set CIBP in slimhole, pump balance plug to at least 6750'. Wait 4 hours, tag plug.)
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 685'. Pump approx 250 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.