

WORKOVER PROCEDURE

WELL NAME: DOMENICO 01 DATE: 8/7/2013

LOCATION: Qtr/Qtr: SWNE Section: 9 Township: 2N Range: 68W

COUNTY: WELD STATE: CO API #: 05-123-10453

ENGINEER: LEAH PERKINS 7 Day Notice Sent: Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 507.6' KB Elevation: 4863
Surface Cmt: 150 sx GL Elevation: 4853
Long St Csg: 4 1/2" @ 7926' (Mix of 10.5# and 11.6#) TD: 7951
Long St Cmt: 400 sx PBTD: 7810
Long St Date: 12/5/1981

Plug Back (Sand or CIBP): Packer @ 7811'
Perforation Interval (1): Niobrara Perfs 7110' - 7242'
Perforation Interval (2): Codell Perfs 7366' - 7389'
Perforation Interval (3): J Sand Perfs 7810' - 7845'
Tubing: 2 3/8" 4.70# J-55 tbg @ 7343' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tbg and lay down.
3) RU WL. RIH w/CIBP. Set CIBP @ 7760', dump bail 2 sx of cement on top.
4) RIH w/ 2nd CIBP. Set CIBP @ 7060', dump bail 2 sx of cement on top.
5) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
6) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
7) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 610'. Pump approx 225 sx shoe plug. Cement to surface.
8) RIH. Tag shoe plug. Add cement if needed.
9) Cut surface casing off 6'-8' below ground.
10) Clean up location. Reclaim location. RDMO.