

WORKOVER PROCEDURE

WELL NAME: UPRC 23-16H4 **DATE:** 8/13/2013
LOCATION:
Qtr/Qtr: NESE Section: 23 Township: 5N Range: 64W
COUNTY: WELD **STATE:** CO **API #:** 05-123-18110

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23# @ 480' KB Elevation: 4601
Surface Cmt: 325 sx GL Elevation: 4590
Long St Csg: 3 1/2" 7.7# B70 @ 7140' TD: 7175
Long St Cmt: 225 sx PBTD: 7077
Long St Date: 3/28/1994

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perfs 6704' - 6790'
Perforation Interval (2): Codell Perfs 6986' - 6995'
Perforation Interval (3): _____
Tubing: 2 1/16" tbg @ 6964' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6604', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 580'. Pump approx 215 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.