

WORKOVER PROCEDURE

WELL NAME: HOSHIKO 01 DATE: 11/16/2013

LOCATION:
Qtr/Qtr: NESE Section: 35 Township: 5N Range: 64W

COUNTY: _____ STATE: _____ CO _____ API #: _____

ENGINEER:	LEAH PERKINS	7 Day Notice Sent:	
	(Please notify Engineer of any major	Do not start operations until:	
	changes prior to work)	Notice Expires:	

OBJECTIVE: _____ P&A

WELL DATA:	Surface Csg:	8 5/8" 24# @ 338'	KB Elevation:	4626
	Surface Cmt:	275 sx	GL Elevation:	4613
	Long St Csg:	4 1/2" 11.60# @ 6809'	TD:	6815
	Long St Cmt:	200 sx	PBTD:	6770
	Long St Date:	3/9/1983		

Plug Back (Sand or CIBP):		
Perforation Interval (1):	Codell Perforations 6726' - 6736'	
Perforation Interval (2):		
Perforation Interval (3):		
Tubing:	2 3/8" 4.70# J-55 @ 6707'	Rods: _____
Pump:	_____	
Misc.:	_____	

PRODUCTION STATUS:	
COMMENTS:	Limited information in well file

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6676', dump bail 2 sx of cement on top.
- 4) Run CBL to determine TOC. (Approx 6000')
- 5) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 440'. Pump approx 160 sx shoe plug. Cement to surface.
- 8) RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.