

WORKOVER PROCEDURE

WELL NAME: JOHNSON 01 **DATE:** 10/21/2013

LOCATION:
Qtr/Qtr: SWSE Section: 11 Township: 6N Range: 66W

COUNTY: WELD **STATE:** CO **API #:** 05-123-12159

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA:

Surface Csg:	<u>8 5/8" 24# @ 306'</u>	KB Elevation:	<u>4847</u>
Surface Cmt:	<u>225 sx</u>	GL Elevation:	<u>4835</u>
Long St Csg:	<u>4 1/2" 11.60# B-70 @ 7352'</u>	TD:	<u>7365</u>
Long St Cmt:	<u>225 sx</u>	PBTD:	<u>7306</u>
Long St Date:	<u>12/16/1984</u>		

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7252' - 7270'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70# J-55 @ 7236' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7202', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 410'. Pump approx 150 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.