

WORKOVER PROCEDURE

WELL NAME: GIBBS 03 **DATE:** 3/27/2013
LOCATION:
Qtr/Qtr: SENE Section: 28 Township: 5N Range: 65W
COUNTY: WELD **STATE:** CO **API #:** 05-123-12768

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 518' KB Elevation: 4669
Surface Cmt: 350 sx GL Elevation: 4656
Long St Csg: 4 1/2" 10.5# @ 7142' TD: 7168
Long St Cmt: 250 sx PBDT: 7092
Long St Date: 11/13/1985'

Plug Back (Sand or CIBP): **CIBP @ 6750' and 6970'**
Perforation Interval (1): Niobrara Perforations 6770' - 6932'
Perforation Interval (2): Codell Perforations 7027' - 7040'
Perforation Interval (3): _____
Tubing: 2 3/8" tbg @ 6435' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 4) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 5) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 620'. Pump approx 250 sx shoe plug. Cement to surface.
- 6) RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.