

WORKOVER PROCEDURE

WELL NAME: HAYTHORN 07-05G5 DATE: 11/21/2013

LOCATION: Qtr/Qtr: SWNW Section: 7 Township: 6N Range: 65W

COUNTY: WELD STATE: CO API #: 05-123-18114

ENGINEER: LEAH PERKINS 7 Day Notice Sent: Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 17# H-40 @ 422' KB Elevation: 4810
Surface Cmt: 168 sx GL Elevation: 4796
Long St Csg: 2 7/8" 6.50# N-80 @ 7308 TD: 7326
Long St Cmt: 100 sx PBTD: 7275
Long St Date: 11/24/1994

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perfs 7186' - 7206'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 1.9" 2.76# J-55 @ 7178' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 1.9" tbg and lay down.
3) RU WL. RIH w/CIBP. Set CIBP @ 7136', dump bail 2 sx of cement on top.
4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 530'. Pump approx 200 sx shoe plug. Cement to surface.
7) RIH. Tag shoe plug. Add cement if needed.
8) Cut surface casing off 6'-8' below ground.
9) Clean up location. Reclaim location. RDMO.