

**FORM**  
**6**  
Rev  
12/05

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number: 400521402			
Date Received: 12/03/2013			

**WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.  
A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120 Contact Name: CHERYL LIGHT  
 Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-6461  
 Address: P O BOX 173779 Fax: (720) 929-7461  
 City: DENVER State: CO Zip: 80217- Email: CHERYL.LIGHT@ANADARKO.COM

**For "Intent" 24 hour notice required,** Name: PRECUP, JIM Tel: (303) 726-3822  
**COGCC contact:** Email: james.precup@state.co.us

API Number 05-123-20296-00 Well Number: 4-12A  
 Well Name: HSR-KUIPERS  
 Location: QtrQtr: NWNW Section: 12 Township: 2N Range: 67W Meridian: 6  
 County: WELD Federal, Indian or State Lease Number: \_\_\_\_\_  
 Field Name: WATTENBERG Field Number: 90750

Notice of Intent to Abandon  Subsequent Report of Abandonment

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 40.158433 Longitude: -104.846133  
 GPS Data:  
 Date of Measurement: 10/21/2008 PDOP Reading: 2.7 GPS Instrument Operator's Name: Cody Mattson  
 Reason for Abandonment:  Dry  Production for Sub-economic  Mechanical Problems  
 Other \_\_\_\_\_  
 Casing to be pulled:  Yes  No Estimated Depth: 1220  
 Fish in Hole:  Yes  No If yes, explain details below  
 Wellbore has Uncemented Casing leaks:  Yes  No If yes, explain details below  
 Details: \_\_\_\_\_

**Current and Previously Abandoned Zones**

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	7798	7840			

Total: 1 zone(s)

**Casing History**

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	727	510	727	0	VISU
1ST	7+7/8	4+1/2	11.6	7,957	270	7,957	6,250	CBL

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7730 with 2 sacks cmt on top. CIBP #2: Depth 7090 with 30 sacks cmt on top.  
CIBP #3: Depth 100 with 30 sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 30 sks cmt from 7090 ft. to 6695 ft. Plug Type: CASING Plug Tagged:   
Set 15 sks cmt from 4120 ft. to 3930 ft. Plug Type: CASING Plug Tagged:   
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:   
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:   
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:

Perforate and squeeze at 4920 ft. with 295 sacks. Leave at least 100 ft. in casing 4120 CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 190 sacks half in. half out surface casing from 1320 ft. to 527 ft. Plug Tagged:

Set 30 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker:  Yes  No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1103  Yes  No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

KUIPERS 4-12A

- 1 Call foreman or lead operator at least 24 hr prior to rig move. Request that they catch and remove the plunger, isolate production equipment and remove any automation prior to rig showing up. Install perimeter fence as needed.
- 2 MIRU slickline servies and VES. Pull bumper spring, tag bottom and run gyro survey from 7710' to surface with stops every 100'. Forward gyro survey data to Sabrina Frantz and invoices to Sabrina Frantz. RDMO slickline services and VES.
- 3 Provide notice of MIRU to COGCC field inspector as specified in approved Form 6.
- 4 Notify IOC when rig mobilizes to location to generate workorder for flowline removal and one call for line locates.
- 5 Prepare location for base beam equipped rig.
- 6 MIRU, kill as necessary using clean fresh water with biocide and circulate. ND WH. NU BOP. Unseat landing jt, LD.
- 7 Notify cementers to be on call. Provide volumes (30 sx "G" w/20% silica flour, 0.4% CD-32, 0.4% ASA-301 and R-3 to achieve 2:30 pump time mixed at 15.8 ppg and 1.38 cf/sk (inside 4.5"), 310 sx class "G", w/0.25 pps cello flake, 0.4% CD-32, 0.4% ASA-301 mixed at 15.8 ppg and 1.15 cf/sx (8"+20% Caliper Log in file); 190 sx Type III CaCl2 cement mixed at 14.0 ppg and 1.53 cf/sx (7.5"+20% Caliper log in file)).
- 8 TOOH 2 3/8" production tubing. Stand back.
- 9 MIRU WL.
- 10 RIH gauge ring for 4.5" 11.6#/ft csg to 7760'.
- 11 RIH CIBP, set at 7730'. PU dump bailer, dump bail 2 sx class "G" cement on CIBP.
- 12 RIH CIBP, set at 7090'. PT CIBP to 1000 psi. RD WL
- 13 TIH to 7090'+/- tag CIBP hydrotesting tubing in to 3000 psi. Roll hole using water containing biocide.
- 14 RU cement services.
- 15 Spot 30 sx "G" w/20% silica flour, 0.4% CD-32, 0.4% ASA-301 and R-3 to achieve 2:30 pump time mixed at 15.8 ppg and 1.38 cf/sk on top of CIBP.
- 16 PUH 15 stands. Circulate 100 BBL water containing biocide to clear tubing.
- 17 Place 9.0 ppg mud containing biocide from 6160' to 5000' (~18BBL). TOOH
- 18 RU WL. PU 2-1' 3-1/8" perf guns with 3 spf, 0.5" dia 120° phasing. Shoot 1' of squeeze holes at 5000' and at 4100'. RD WL.
- 19 PU CICR on production tubing and set at 4130'. Initiate circulation through CICR using water containing biocide. Note rate and pressure.
- 20 RU cement services.
- 21 Pump 20 bbl Sodium Metasilicate immediately preceding cement.
- 22 Pump 310 sx class "G", w/0.25 pps cello flake, 0.4% CD-32, 0.4% ASA-301 mixed at 15.8 ppg and 1.15 cuft/sx. Underdisplace by 3 bbls, unsting from retainer and dump remaining on top of CICR.
- 23 PUH 7 stands. Reverse circulate 30 BBL water containing biocide to clear tubing.
- 24 Place 9.0 ppg mud containing biocide from 3696' to 1320' (~37BBL).
- 25 P&SB 1320' tbg. LD remainder.
- 26 RU WL. Crack coupling or shoot off casing at 1220'. RDMO WL. Circulate hole using 80 BBL water containing biocide to remove any gas.
- 27 NDBOP, NDTH.
- 28 NU BOP on casing head, install 4-1/2" pipe rams.
- 29 TOOH with 4-1/2" casing, LD.
- 30 TIH into csg stub using production tubing to 1320'.
- 31 Spot 190 SX Type III CaCl2 cement mixed at 14.0 ppg and 1.53 cuft/sx.
- 32 PUH to 400'. Circulate 20 BBLs water containing biocide to clear tubing.
- 33 TOOH. WOC 4 hrs.
- 34 TIH and tag. If cement is below 527', discuss with production engineer.
- 35 Fill casing with 9.0 ppg mud containing biocide from tag to 100'.
- 36 MIRU WL. RIH 8-5/8" CIBP to 100'. Set, PT to 1000 psi for 15 min. If tests, RDMO WL and WO rig.
- 37 Supervisor submit paper copies of all invoices, logs, and reports to Frantz, Sabrina.
- 38 Excavation crew to notify One Call to clear excavation area around wellhead and for flowlines.
- 39 Excavate hole around surface casing enough to allow welder to cut 8 5/8" casing minimum 5' below ground level.
- 40 Welder cut 8 5/8" casing minimum 5' below ground level.
- 41 MIRU ready cement mixer. Use 4500psi compressive strength cement, (NO gravel) fill stubout.
- 42 Weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: CHERYL LIGHT  
 Title: SR. REGULATORY ANALYST Date: 12/3/2013 Email: DJREGULATORY@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SCHLAGENHAUF, MARK Date: 12/7/2013

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_ Expiration Date: 6/6/2014

<u>COA Type</u>	<u>Description</u>
	1) Submit Form 42 electronically to COGCC 48 hours prior to MIRU. 2) If unable to pull casing, contact COGCC for plugging modifications. 3) Leave at least 100' cement in the wellbore for each plug. 4) For 1320' plug: pump plug and displace, shut-in, WOC 4 hours and tag plug – must be 677' or shallower. 5) Properly abandon flowlines as per Rule 1103.

**Attachment Check List**

<u>Att Doc Num</u>	<u>Name</u>
400521402	FORM 6 INTENT SUBMITTED
400521407	PROPOSED PLUGGING PROCEDURE
400521414	WELLBORE DIAGRAM
400521415	WELLBORE DIAGRAM

Total Attach: 4 Files

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Well completion report dated 10/18/2001.	12/6/2013 10:17:36 AM

Total: 1 comment(s)