

WORKOVER PROCEDURE

WELL NAME: GOZA FEDERAL 18-01 **DATE:** 12/11/2013

LOCATION:
Qtr/Qtr: NESE Section: 18 Township: 6N Range: 65W

COUNTY: WELD **STATE:** CO **API #:** 05-123-15612

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 462' KB Elevation: 4760
Surface Cmt: 240 sx GL Elevation: 4749
Long St Csg: 3 1/2" 9.2# @ 7254' TD: 7261
Long St Cmt: 200 sx PBSD: 7182
Long St Date: 3/7/1992

Plug Back (Sand or CIBP): **RBP @ 6887' w/ sand plug on top**
Perforation Interval (1): Codell Perfs 7100' - 7110'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: _____ Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RIH w/ workstring, circulate sand plug off RBP. POOH w/ RBP.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7050', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 570'. Pump approx 210 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.