

WORKOVER PROCEDURE

WELL NAME: KISSLER K21-1 **DATE:** 12/11/2013
LOCATION:
Qtr/Qtr: NENE Section: 21 Township: 4N Range: 66W
COUNTY: WELD **STATE:** CO **API #:** 05-123-15376

ENGINEER: SETH GORDON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 318' KB Elevation: 4757'
Surface Cmt: 300 SX GL Elevation: 4745'
Long St Csg: 2 7/8" 6.5# @ 7403' TD: 7418'
Long St Cmt: 275 SX PBTD: 7400'
Long St Date: 11/19/1991

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7257" - 7273'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 1/2" tbg @ 7241' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/2" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7207', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 418'. Pump approx 160 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.