

WORKOVER PROCEDURE

WELL NAME: WASTE MANAGEMENT USX Y #3-13 **DATE:** 12/11/2013
LOCATION:
Qtr/Qtr: SWSW Section: 3 Township: 2N Range: 64W
COUNTY: WELD **STATE:** CO **API #:** 05-123-24798

ENGINEER: SETH GORDON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 905' KB Elevation: 4889'
Surface Cmt: 441 sx GL Elevation: 4879'
Long St Csg: 4 1/2" 11.6# @ 7630' TD: 7638'
Long St Cmt: 830 sx PBTD: 7612'
Long St Date: 6/1/2007

Plug Back (Sand or CIBP): _____
Perforation Interval (1): J Sand Perforations 7492' - 7512'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" tubing @ 7473' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7442', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) POOH w/workstring to 1005'. Pump approx 400 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.