

WORKOVER PROCEDURE



WELL NAME: STEPHENS 01 DATE: 12/30/2013

LOCATION: Qtr/Qtr: SWNW Section: 15 Township: 4N Range: 66W

COUNTY: WELD STATE: CO API #: 05-123-11552

ENGINEER: LEAH PERKINS 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 406' KB Elevation:
Surface Cmt: 300 sx GL Elevation: 4732
Long St Csg: 5 1/2" 20# @ 7850' TD: 7850
Long St Cmt: 225 sx PBTD: 7810

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perfs 7235' - 7243'
Perforation Interval (2):
Perforation Interval (3):
Tubing: Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ tbg and lay down.
3) RU WL. RIH w/CIBP. Set CIBP @ 7185', dump bail 2 sx of cement on top.
4) Run CBL to confirm cement tops.
5) Perforate @ 5000' and set CICR @ 4950'. Pump 90 sx through CICR, 10 sx on top.
6) POOH w/workstring to 600'. Pump approx 475 sx shoe plug. (Either perforate or fill back side by annular fill). Cement to surface.
7) RIH. Tag shoe plug. Add cement if needed.
8) Cut surface casing off 6'-8' below ground.
9) Clean up location. Reclaim location. RDMO.