

WORKOVER PROCEDURE

WELL NAME: DAVIS 1 **DATE:** 1/7/2014

LOCATION: Qtr/Qtr: NESW Section: 20 Township: 1S Range: 66W

COUNTY: ADAMS **STATE:** CO **API #:** 05-001-06809

ENGINEER: SETH GORDON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA:	Surface Csg:	<u>8 5/8" 24# @ 132'</u>	KB Elevation:	<u>5050</u>
	Surface Cmt:	<u>120 sx</u>	GL Elevation:	<u>5040</u>
	Long St Csg:	<u>4 1/2" 11.6# @ 8231'</u>	TD:	<u>8234'</u>
	Long St Cmt:	<u>250 sx</u>	PBTD:	<u>8162'</u>
	Long St Date:	<u>3/24/1974</u>		

Plug Back (Sand or CIBP): _____
Perforation Interval (1): J Sand Perforations 8123' - 8158'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 1/2" 8120' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) Tag, need to be able to get down to 8073' w/ CIBP. POOH w/ 1 1/2" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 8073', dump bail 2 sx of cement on top.
- 4) Run CBL from CIBP to surface to verify long string cement top and 300 sx pumped through DV tool @ 1203'.
- 5) If long string cement top is 7070' or higher, proceed to step 6.
If not, RIH, perf 100' above TOC, RIH with CICR, circulate 90 sx through, 10 on top.
- 6) RIH, perf 10 feet above top of DV tool cement (estimated at 150', verify on CBL).
- 7) RIH w/ workstring to 1300'. Pump 110 sx balance plug. POOH w/ tubing.
- 8) Pump 75 sx down backside circulating up casing to surface. Shut in, WOC 4 hours.
- 9) RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.