

WORKOVER PROCEDURE

WELL NAME: BERIG STATE K36-29 **DATE:** 1/13/2014
LOCATION:
Qtr/Qtr: NENW Section: 36 Township: 4N Range: 66W
COUNTY: WELD **STATE:** CO **API #:** 05-123-25632

ENGINEER: SETH GORDON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 479' KB Elevation: 4824'
Surface Cmt: 251 sx GL Elevation: 4811'
Long St Csg: 4 1/2" 11.6# @ 7486' TD: 7493'
Long St Cmt: 900 sx PBDT: 7461'
Long St Date: 3/18/2008

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 7064' - 7158'
Perforation Interval (2): Codell Perforations 7354' - 7364'
Perforation Interval (3): _____
Tubing: 2 3/8" @ 7336' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7014', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 700'. POOH laying casing down on trailer.
- 5) RIH w/ workstring to pump 275 sx stub/shoe plug where csg was pulled. Cement to surface.
- 6) WOC 4 hours. RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.