

WORKOVER PROCEDURE

WELL NAME: ANDERSON E24-14 DATE: 2/6/2013

LOCATION: Qtr/Qtr: SESW Section: 24 Township: 6N Range: 65W

COUNTY: WELD STATE: CO API #: 05-123-16470

ENGINEER: LEAH PERKINS SETH GORDON 7 Day Notice Sent: Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 306' KB Elevation: 4695 Surface Cmt: 200 sx GL Elevation: 4686 Long St Csg: 2 7/8" 6.5# @ 7109' TD: 7110 Long St Cmt: 240 sx PBSD: 6868 Long St Date: 4/16/1998

Plug Back (Sand or CIBP): CIBP @ 6883'. Sand Plug 6868' - 6883' Perforation Interval (1): Codell Perforations 6933' - 6947' Perforation Interval (2): Perforation Interval (3): Tubing: Rods: Pump: Misc.: Csg repair 4/98. Patch @ 4606'

PRODUCTION STATUS: COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank. 2) RIH w/ workstring. Circulate to remove sand plug. Pump 5 sx plug above CIBP @6883'. 3) Unland casing. Cut casing off +/- 4500'. POOH with casing laying down on trailer. 4) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug. 5) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 410'. Pump approx 200 sx shoe plug. Cement to surface. 6) RIH. Tag shoe plug. Add cement if needed. 7) Cut surface casing off 6'-8' below ground. 8) Clean up location. Reclaim location. RDMO.