

WORKOVER PROCEDURE

WELL NAME: SCHMIDT 25-16F **DATE:** 2/5/2014

LOCATION: _____

Qtr/Qtr: SESE Section: 25 Township: 4N Range: 66W
COUNTY: _____ **STATE:** CO **API #:** 05-123-14945

ENGINEER: SETH GORDON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23# @ 503' KB Elevation: 4807'
Surface Cmt: 320 sx GL Elevation: 4797'
Long St Csg: 4 1/2" 11.6# @ 7342' TD: 7346'
Long St Cmt: 200 sx Sussex/200 sx C/N PBTD: 7300'
Long St Date: 4/6/1991

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6948' - 7128'
Perforation Interval (2): Codell Perforations 7248' - 7263'
Perforation Interval (3): _____
Tubing: 2 3/8" J-55 @ 7233' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6898', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 4650'. Pump 35 sx balance plug. POOH.
- 5) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 600'. Pump approx 225 sx shoe plug. Cement to surface.
- 8) WOC 4 hours. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.