

WORKOVER PROCEDURE

WELL NAME: LILLI UNIT 15-5 **DATE:** 2/28/2014

LOCATION:
Qtr/Qtr: SWSE Section: 5 Township: 8N Range: 58W

COUNTY: WELD **STATE:** CO **API #:** 05-123-13339

ENGINEER: SETH GORDON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 162' KB Elevation: 4745'
Surface Cmt: 100 sx GL Elevation: 4736'
Long St Csg: 4 1/2" 10.5# @ 6524' TD: 6530'
Long St Cmt: 180 sx PBTD: 6513'
Long St Date: 2/10/1987

Plug Back (Sand or CIBP): _____
Perforation Interval (1): J Sand Perforations 6356' - 6376'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: None Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

- PROCEDURE:**
- 1) MIRU Workover rig, pump & tank.
 - 2) RIH w/ workstring and retrieving head.
 - 3) Wash down, tag sand (~6300'). Circulate clean to RBP, latch on, POOH w/ RBP.
 - 4) RU WL. RIH w/CIBP. Set CIBP @ 6306', dump bail 2 sx of cement on top.
 - 5) Perforate @ 5700' and set CICR @ 5650'. Pump 40 sx through CICR and 10 sx above CICR.
 - 6) Perforate @ 2500' and set CICR @ 2450'. Pump 90 sx through CICR and 10 sx above CICR.
 - 7) Cut casing off 700'. POOH with casing laying down on trailer.
 - 8) RIH w/ workstring to pump 325 sx stub/shoe plug where csg was pulled. Cement to surface.
 - 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
 - 10) Cut surface casing off 6'-8' below ground.
 - 11) Clean up location. Reclaim location. RDMO.