

WORKOVER PROCEDURE

WELL NAME: LILLI UNIT 16-34 **DATE:** 2/28/2014
LOCATION:
Qtr/Qtr: SESE Section: 34 Township: 9N Range: 58W
COUNTY: WELD **STATE:** CO **API #:** 05-123-13991

ENGINEER: SETH GORDON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 178' KB Elevation: 4753'
Surface Cmt: 105 sx GL Elevation: 4743'
Long St Csg: 4 1/2" 10.5# @ 6423' TD: 6425'
Long St Cmt: 190 sx PBTD: 6410'
Long St Date: 6/21/1988

Plug Back (Sand or CIBP): _____
Perforation Interval (1): D Sand Perforations 6284' - 6294'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: None Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RIH w/ workstring and retrieving head.
- 3) Wash down, tag sand (~6231'). Circulate clean to RBP, latch on, POOH w/ RBP.
- 4) RU WL. RIH w/CIBP. Set CIBP @ 6234', dump bail 2 sx of cement on top.
- 5) Perforate @ 5500' and set CICR @ 5450'. Pump 70 sx through CICR and 10 sx above CICR.
- 6) Perforate @ 2500' and set CICR @ 2450'. Pump 90 sx through CICR and 10 sx above CICR.
- 7) Cut casing off at 1000'. POOH with casing laying down on trailer.
- 8) RIH w/ workstring to pump 425 sx stub/shoe plug where csg was pulled. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.