

WORKOVER PROCEDURE

WELL NAME: CPC BEEBE DRAW 11-01 **DATE:** 2/21/2014
LOCATION:
Qtr/Qtr: NWNE Section: 11 Township: 3N Range: 65W
COUNTY: WELD **STATE:** CO **API #:** 05-123-13346

ENGINEER: GREG ANDERSON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 318' KB Elevation: 4820
Surface Cmt: 225 sx GL Elevation: 4809
Long St Csg: 4 1/2" 15.1# Grd E @ 7208' TD: 7233
Long St Cmt: 175 sx PBTD: 7147
Long St Date: 2/25/1987

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6813' - 6982'
Perforation Interval (2): Codell Perforations 7096' - 7109'
Perforation Interval (3): _____
Tubing: 2 3/8" tbg @ 7086' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6763', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 4500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) POOH w/workstring to 2500'. Pump approx 50 sx courtesy plug.
- 7) WOC 4 hours. Tag cement.
- 8) POOH w/workstring to 500' (deepest water @ 400'). Pump approx 200 sx shoe plug. Cement to surface.
- 9) If cement not circulated in step 8: WOC 4 hours. RIH. Tag shoe plug. Add cement if needed. Cement must be 218' or sh
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.