

## WORKOVER PROCEDURE

**WELL NAME:** FEIT E23-16 **DATE:** 3/10/2014  
**LOCATION:**  
Qtr/Qtr: SE/SE Section: 23 Township: 6N Range: 65W  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-16796

**ENGINEER:** JONATHAN POMERANTZ 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 306' KB Elevation: 4703'  
Surface Cmt: 300 sx GL Elevation: 4694'  
Long St Csg: 2 7/8" 6.5# @ 7149' TD: 7152'  
Long St Cmt: 240 sx + 465 sx PBTD: 7145'  
Long St Date: 3/6/1993

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 6984' - 6998'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1 15/16" 2.75# J-55 tbg @ 6963' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 15/16" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6934', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to pump 50 sx balance plug @ 5400'. SI, WOC. RIH to tag balance plug @ approx 3600'.
- 5) POOH w/workstring to 600'. Pump approx 20 sx shoe plug. Cement to surface.
- 6) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.