

WORKOVER PROCEDURE

WELL NAME: DANIELS K05-14X DATE: 3/5/2014

LOCATION: Qtr/Qtr: SE/SW Section: 5 Township: 4N Range: 66W

COUNTY: WELD STATE: CO API #: 05-123-20058

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 390' KB Elevation: 4710' Surface Cmt: 295 sx GL Elevation: 4699' Long St Csg: 4 1/2" 11.6# @ 7319' TD: 7320' Long St Cmt: 305 sx PBTD: 7297' Long St Date: 10/6/2000

Plug Back (Sand or CIBP): Perforation Interval (1): Codell Perforations 7164' - 7180' Perforation Interval (2): Perforation Interval (3): Tubing: 2 3/8" 4.7# J-55 tbg @ 7134' Rods: Pump: Misc.:

PRODUCTION STATUS: COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank. 2) POOH w/ 2 3/8" tbg and lay down. 3) RU WL. RIH w/CIBP. Set CIBP @ 7114', dump bail 2 sx of cement on top. 4) Unland casing. Cut casing off @ 4360'. POOH with casing laying down on trailer. 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug. 6) Pump 50 sx courtesy plug @ 2500'. POOH w/workstring to 510'. Pump approx 175 sx shoe plug. Cement to surface. 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed. 8) Cut surface casing off 6'-8' below ground. 9) Clean up location. Reclaim location. RDMO.