

WORKOVER PROCEDURE

WELL NAME: FOSS 06-33 **DATE:** 3/5/2014

LOCATION:
Qtr/Qtr: SW/SW Section: 6 Township: 6N Range: 63W

COUNTY: WELD **STATE:** CO **API #:** 05-123-23512

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 440' KB Elevation: 4718'
Surface Cmt: 210 sx GL Elevation: 4708'
Long St Csg: 4 1/2" 11.6# @ 7061' TD: 7068'
Long St Cmt: 160 sx PBSD: 7045'
Long St Date: 3/6/2006

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6680' - 6700'
Perforation Interval (2): Codell Perforations 6857' - 6868'
Perforation Interval (3): _____
Tubing: 2 3/8" ?# ? Tbg @ 6829' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

- PROCEDURE:**
- 1) MIRU Workover rig, pump & tank.
 - 2) POOH w/ 2 3/8" tbg and lay down.
 - 3) RU WL. RIH w/CIBP. Set CIBP @ 6630', dump bail 2 sx of cement on top.
 - 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
 - 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
 - 6) POOH w/workstring to 560'. Pump approx 200 sx shoe plug. Cement to surface.
 - 7) RIH. Tag shoe plug. Add cement if needed.
 - 8) Cut surface casing off 6'-8' below ground.
 - 9) Clean up location. Reclaim location. RDMO.