

WORKOVER PROCEDURE

WELL NAME: UPV 27-04G3 **DATE:** 3/7/2014

LOCATION: _____

Qtr/Qtr: NW/NW Section: 27 Township: 6N Range: 63W
COUNTY: WELD **STATE:** CO **API #:** 05-123-18633

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 17# @ 424' KB Elevation: 4757'
Surface Cmt: 144 sx GL Elevation: 4746'
Long St Csg: 2 7/8" 6.5# @ 6939' TD: 6960'
Long St Cmt: 125 sx PBTD: 6907'
Long St Date: 10/23/1994

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6514' - 6624'
Perforation Interval (2): Codell Perforations 6775' - 6795'
Perforation Interval (3): _____
Tubing: 1 1/4" 2.4# J-55 tbg @ 6759' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/4" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6464', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 4600'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) POOH w/ workstring to 2500'. Pump 50 sx courtesy plug. SI, WOC. RIH. Tag balance plug @ approx 2280'.
- 7) POOH w/workstring to 580'. Pump approx 150 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.