

WORKOVER PROCEDURE

WELL NAME: BASHOR 17-42 **DATE:** 3/24/2014
LOCATION:
Qtr/Qtr: NW/SE Section: 17 Township: 6N Range: 63W
COUNTY: WELD **STATE:** CO **API #:** 05-123-23437

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" ?# @ 488' KB Elevation: 4684'
Surface Cmt: 225 sx GL Elevation: 4674'
Long St Csg: 4 1/2" 11.6# @ 6912' TD: 6930'
Long St Cmt: 150 sx PBTD: 6895'
Long St Date: 3/13/2006

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6600' - 6622'
Perforation Interval (2): Codell Perforations 6790' - 6800'
Perforation Interval (3): _____
Tubing: 2 3/8" ?# ? tbg @ 6767' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6550', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 4500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 600'. Pump approx 200 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.